

Assembly fittings

for pressure gauges and pressure transmitters

Mounting bracket and Adaptor

E 09.06.01


Ed.12.01

Surface mounting bracket

Surface mounting brackets are intended to provide a means of surface mounting where the thermometer or the pressure gauge itself can not be equipped with suitable provisions.

Used together with adaptor.

Type	Length	Material	Weight	Code
9184	60	aluminium	0,15	91840000
9185	100	aluminium	0,18	91850000
9186	160	aluminium	0,26	91860000
9187	60	1.4571	0,17	91870000
9188	100	1.4571	0,21	91880000
9189	160	1.4571	0,26	91890000



Adaptor

Adaptors are intended to provide a means of surface mounting where the thermometer or the pressure gauge itself can not be equipped with suitable provisions.

Used together with surface mounting bracket.

Type	Conn.	Material	Weight	Code
9076	G1/2"	brass	0,25	90760000
9077	G1/2"	steel	0,23	90770000
9127	G1/2"	1.4571	0,23	91270000
9141	1/2"NPT	1.4571	0,23	91410000

